



## Cultural Resource Consultants

---

### Memorandum

**To:** William Lee, Gowanus Environmental Remediation Trust #2

**From:** Michael Audin, RPA & Nicholas Zeitlin, RPA

**Date:** September 6, 2022

**RE:** Memo # 27 - Results of Level 2 Cultural Resource Review  
Debris Staging at Clean Earth – Claremont  
RTA-1 Dredging, Level 2 Monitoring  
Gowanus Canal Remediation Project  
Brooklyn, Kings County, NY

---

This memorandum presents the findings of Archaeology & Historic Resource Services, LLC's (AHRS) review of screened sediments at the Clean Earth Claremont Facility in Jersey City, New Jersey (Clean Earth) from Level 2 Monitoring. The screened sediments are from the RTA-1 dredging currently underway at the Gowanus Canal Superfund Site in Brooklyn, New York. The purpose of this memorandum is to present the results and recommendations for the items recovered from sediment screening at Clean Earth reviewed by an AHRS archaeologist on 9/1/2022. The attached Figure provided by the Trust indicates the approximate area that was dredged between 8/29/2022 and 9/1/ 2022.

### INTRODUCTION

Cashman Dredging and Marine Contracting Co. (Cashman) continues with the dredging of soft sediments from RTA-1 under the oversight of the EPA. The dredge material is being processed according to the Level 2 Archaeological Monitoring protocol outlined in the draft Cultural Resource Monitoring Plan (revised September 2020). This protocol calls for dredged soft sediments to be placed directly into scows, floated to Clean Earth, and screened over 4" bars on a vibrating platform. Items removed during the vibratory screening process are then sorted by the Clean Earth operator as per the Cultural Resource Monitoring Plan. Items of potential interest (possible artifacts or objects of local interests) are placed in a separate stockpile and photographed daily for AHRS archaeologists to review. These items are then placed in a holding area for AHRS to inspect weekly.

### RESULTS

AHRS archaeologist Nicholas Zeitlin conducted a scheduled site visit on 9/1/22 to review the recovered items in person with the assistance of a Clean Earth machine and operator to sort through stockpiled material (Photograph 1). Photographs were taken of stockpiled material and retained items at Clean Earth.

The recovered material was spread by machine on a flat hard surface to allow for an archaeologist to clearly review it. The reviewed material was comprised of mostly oily mud with debris comprised of concrete, wood, rocks, tires and miscellaneous metal (Photograph 2, 3, 4). No items of potential interest were observed.



**Photograph 1** – View of debris pile to be reviewed, front view.





**Photograph 2** – Close up of the condition of the material to be reviewed, front view.



**Photograph 3** – View of concrete, wood, tire and metal front view.





**Photograph 4** – Example of rocks, front view.


#### Items Segregated for Further Review

AHRS archaeologist retained no items.

#### **CONCLUSIONS AND RECOMMENDATIONS**

AHRS concludes that no items observed during the sediment screening at Clean Earth were of interest or retained. AHRS further recommends that all the non-historically/archaeologically significant debris at Clean Earth has been reviewed by the AHRS archaeologist as of 9/1/2022 may be disposed of.





**Figure 1** - Approximate areas of Phase III material dredged north of 3<sup>RD</sup> Street Bridge between August 29 and September 1, 2022.